AMENDMENT TO DRAWINGS (FIG. 8)

Reference Number "95"

In the original Fig. 8, Reference Number "95" incorrectly marked the wrong structure in

Fig. 8. As shown in the Annotated Marked-Up Diagram for Fig. 8, the applicant has redrawn

Ref. No. "95" to properly indicate the first inner casing surface 95. The proper antecedent

basis for this amendment is found in the Specification, page 8, lines 7-10, and Fig. 3. This was

an inadvertent error by the applicant, and this amendment was not made in response to any

action by the Examiner. No new matter has been added.

Reference Number "105"

In the original Fig. 8, Reference Number "105" incorrectly marked the wrong structure

in Fig. 8. As shown in the Annotated Marked-Up Diagram for Fig. 8, the applicant has

redrawn Ref. No. "105" to properly indicate the third inner casing surface 105. The proper

antecedent basis for this amendment is found in the Specification, page 8, lines 7-10, and Fig. 3.

This was an inadvertent error by the applicant, and this amendment was not made in response

to any action by the Examiner. No new matter has been added, and the applicant respectfully

requests consideration.

Respectfully Submitted,

LAW OFFICE OF DAVID HONG

Bv

Dated: May 21, 2004

David Hong (Reg. No. 45,704)

2